

JOB SAFETY ANALYSIS

Safety Information for the University of California, Berkeley

DEPARTMENT OF MECHANICAL ENGINEERING

OPERATING A CNC LATHE

TASK	HAZARDS	CONTROLS
1. Assess work area; is it clear of obstructions and slip/trip/fall hazards?	<ul style="list-style-type: none">Slip, trip, or fall	<ul style="list-style-type: none">Clear work area of any obstructions or slip/trip/fall hazards
2. Install all of the required tooling for a job into the turret	<ul style="list-style-type: none">Lacerations to fingers/hands from the toolPinching hazards for fingers/handsTools coming loose while cutting	<ul style="list-style-type: none">Handle cutting tools with care; avoid sharp edgesKeep fingers and hands free from pinch pointsEnsure the tool is secured in its holder before loading it into the turret
3. Load material into the chuck	<ul style="list-style-type: none">Lacerations to fingers/hands from the materialPinching hazards for fingers/handsMaterial dislodged from the chuck while cuttingMuscle fatigue	<ul style="list-style-type: none">Deburr material before handling, never run hands along edgeKeep fingers and hands free from pinch points; specifically when tightening and loosening the chuck jawsEnsure the material is tightly secured in the chuck before turning the spindle onPosition body to maintain balance, maximize use of legs, and ask for assistance if necessary
4. Set the work coordinate system for each tool in both the X and Z axis of the machine	<ul style="list-style-type: none">Crashing the machineEye injury from flying debris	<ul style="list-style-type: none">Work slowly and deliberately. Use appropriate jog increments and spindle speed when setting toolsOnly operate machine with doors closed, wear safety glasses at all times when operating machine

	5. Load G-code onto machine and dry run through program	<ul style="list-style-type: none"> • Crashing the machine • Eye injury from flying debris 	<ul style="list-style-type: none"> • Add a minimum of 3 inches to your X and Z-axis offsets so all tools run in the air and well above the part. Reduce the Rapid Overrides on the machine to 25% maximum. Reduce the feed rate to 50% maximum. Always be ready to hit the E-Stop button. • Only operate machine with doors closed, wear safety glasses at all times when operating machine
	6. Return X and Z-axis offsets to where they were first established and run through the entire program	<ul style="list-style-type: none"> • Crashing the machine • Operator entanglement • Material dislodged from the chuck when cutting • Eye injury from flying debris • Excessive noise levels 	<ul style="list-style-type: none"> • Never leave the machine running unattended. Reduce feed and rapids if necessary to allow operator to reactor more quickly. Always be ready to hit the E-Stop button. • Never run the spindle with the doors to the machine open. Enable E-Stop when reaching into machine. • Ensure chuck is securely clamped onto the work. • Only operate machine with doors closed, wear safety glasses at all times when operating machine • Wear ear plugs/muffs if necessary
	7. Remove finished work piece and clean the machine	<ul style="list-style-type: none"> • Lacerations to hands/fingers from chips • Lacerations to hands/fingers from the cut part • Eye injury from flying debris 	<ul style="list-style-type: none"> • Never brush chips away with bare hands or fingers. Use a chip brush or pliers to remove chips. • Always deburr your parts before handling. Be cautious of extremely sharp edges produced from the cutting process. • Do not use compressed air to clean table. Use a chip brush and coolant spigot.
	8. Remove all tool holders from the turret	<ul style="list-style-type: none"> • Pinching hazards • Lacerations to hands/fingers from bit 	<ul style="list-style-type: none"> • Keep hands free from pinch points; particularly when unloading the tool from the spindle • Handle tool bit with care; avoid sharp edges

<p>Other Information:</p> <p>Contributors:</p> <p>Created:</p> <p>Updated:</p> <p>JSA Library Number:</p>	<p>Required Training:</p> <p>Student Shop Safety Training Program</p> <p>Must complete additional training under guidance of a qualified Student Shop Laboratory Mechanician</p>	<p>Required Personal Protective Equipment (PPE)</p> <p>Safety glasses</p>
	<p>Mori Seiki DuraTurn 1530 User Manual</p> <p>ME Pro Shop, Scott G. McCormick; R&D Engineering Manager, Jacob Gallego; Principal Lab. Mech.</p> <p>Jan. 2007</p> <p>July 2020</p> <p>(EH&S will insert number here, if applicable)</p> <p>For more information about this JSA, contact the <i>Office of Environment, Health and Safety</i> at UC Berkeley, 317 University Hall #1150, Berkeley, CA 94720-1150 (510) 642-3073 • http://www.ehs.berkeley.edu</p>	