JOB SAFETY ANALYSIS

Safety Information for the University of California, Berkeley

DEPARTMENT OF MECHANICAL ENGINEERING OPERATING A VERTICAL MILLING MACHINE

	TASK	HAZARDS	Controls
1.	Assess work area; is it clear of obstructions and slip/trip/fall hazards?	Slip, trip, or fall	Clear work area of any obstructions or slip/trip/fall hazards
2.	Install vise or work piece.	 Pinching hazard for hands/fingers Foot injury from dropping of heavy objects 	 Avoid pinch points Position body to maintain balance, maximize use of legs, and ask for assistance if necessary
3.	Insert end mill into collet (or insert drill bit into drill chuck), then install it in the spindle of the milling machine.	 Pinching hazards Lacerations to hands/fingers from bit Misalignment of drill bit in chuck Cutter dislodged from collet 	 Keep hands free from pinch points Handle tool bit with care; avoid sharp edges Ensure all 3 chuck jaws are making contact with the bit Ensure the cutter is tightly secured in the collet before turning on the spindle
4.	Adjust the gear and speed of the spindle for your application	Pinching hazard for hands/fingers	Avoid pinch points
5.	Turn on spindle	 Cutter dislodged from collet Lacerations to hands/fingers from rotating cutter Operator entanglement 	 Ensure the cutter is tightly secured in the collet before turning on the spindle Do not place your hands or fingers anywhere near the rotating cutter Never wear loose clothing when operating, tie hair back, tuck in drawstrings, and remove jewelry.

(insert JSA Library # here)

	6. Feed cutter into workpiece	 Lacerations to hands/fingers from rotating cutter Eye injury from flying debris Material dislodged from the vise Lacerations to hands/fingers from chips Burning hazards from chips Lacerations to hands/fingers from the cut part Excessive noise 	 Do not place your hands or fingers anywhere near the rotating cutter Always wear safety glasses when operating equipment Ensure the material is securely fastened in vise before making a cut Never brush chips away with bare hands or fingers. Use a chip brush or pliers to remove chips. Stand to the side of the cut or use a chip shield; hot chips can burn skin Always deburr your parts before handling Wear ear plugs/muffs if necessary
	7. Turn off machine and remove cutter	Pinching hazardsLacerations to hands/fingers from bit	 Keep hands free from pinch points Handle tool bit with care; avoid sharp edges
	8. Remove finished work piece and clean machine	 Lacerations to hands/fingers from chips Lacerations to hands/fingers from the cut part Eye injury from debris 	 Never brush chips away with bare hands or fingers. Use a chip brush or pliers to remove chips. Always deburr your parts before handling Do not use compressed air to clean table. Use a chip brush and wipe up excess oil.
	Required Training:	Required Personal Protective Equipment (PPE)	
	Student Shop Safety Training Program (<i>Phase 3</i>)	Safety glasses, ear plugs/muffs	
Other Information: Contributors: Created: Updated: JSA Library Number:	ME Pro Shop, Scott G. McCormick; R&D Engineering Manager, Jacob Gallego; Principal Lab. Mech. Jan. 2007 July 2020		

(insert JSA Library # here)